



Sensor not  
Shown to Scale

## Features

- Indoor/outdoor temperature (°F/°C)
- Indoor/outdoor humidity (%RH)
- MIN/MAX temperature & humidity records
- 6 Moon phase icons
- Sensor signal strength indicator
- Customizable indoor/outdoor temperature alerts (HI/LO/OFF)
- Temperature trend indicators
- 12/24 Hour time display
- Alarm with snooze
- Calendar: month, day, date
- Low battery indicator: Display & Sensor

## Specifications

- **Sensor:** TX141TH-A
- **Indoor Temperature Range:** 32°F to 122°F (0°C to 50°C)
- **Outdoor Temperature Range:** -40°F to 140°F (-40°C to 60°C)
- **Humidity Range:** 10% to 99% (%RH)
- **Transmission Range:** Over 300 ft. (91m)

## Power Requirements

- **Station:** 2 "AA" Alkaline batteries (not included)
- **Sensor:** 2 "AA" Alkaline batteries (not included)

## Dimensions

- **Station:** 5.40" L x 1.69" W x 4.40" H
- **Sensor:** 1.57" L x 0.79" W x 5.12" H
- **Package:** 8.50" L x 2.15" W x 9.35" H

## Sales Information

- **Model No.** 308-1711BL
- **UPC:** 7 57456 98530 5
- **MSRP:** \$38.95
- **Inner Pack:** 4
- **Master Pack:** 16

## Packaging

Open-Face Blister Box

