

Directions:

Use in a well-ventilated area. Protect work surfaces.

- 1. Surfaces to be repaired should be clean and dry.
- 2. POINT TUBE AWAY FROM FACE AND BODY. Unscrew cap and pierce tube with point on outer cap.
- 3. Apply Porcelain Chip Fix to damaged area and carefully level it with a straight edge.
- 4. Allow to dry for 10 minutes. If more than one coat is required, let it dry overnight.
- 5. Use nail polish remover or acetone to remove excess Porcelain Chip Fix. Replace cap for storage after use.

NOTE: Do not sand or buff cured material. Not suitable for rusty surfaces or large gaps. Not paintable. This product is not intended to be used on ovens, stoves or other surfaces subjected to high heat.