



Directions:

NOTE: For best results, surfaces should be clean & dry and parts should mate well.

1. Protect clothing and work surfaces (metal foil works well). Use in a well-ventilated area. Keep container pointed away from face and body. Carefully follow opening directions on package. Unscrew cap while keeping container pointed away from face.

2. Apply to one surface, using 1 drop per square inch of surface. Do not spread glue with fingers – use applicator nozzle tip. Assemble parts and hold together with pressure for 15 seconds or until set.

3. Wipe tip if adhesive has accumulated before resealing cap securely.